

Fig.1




Fig.2




FIG. 1

2/15




Fig. 3a




Fig. 3b

Fig. 4





Fig. 5



09/ 831364 02/15

3/15








Fig. 8

Fig. 9

Fig. 10

4/15

Fig.10




Fig.11





Fig.12



5/15

Fig.13




Fig.14





Fig.15



106280" 49E1E860

WO 00/31758

PCT/FR99/02771

6/15

Fig.16




Fig.17




Fig.18





Fig.19



09831364-082901

WO 00/31758

PCT/FR99/02771

7/15




Fig. 20




Fig. 21




Fig. 22




Fig. 23

09/831364-1921E360

8/15




Fig. 24




Fig. 25








Fig. 26

09831364-082901

WO 00/31758

9/15



09/831364 SHEET 9 OF 10

WO 00/31758

10/15




Fig.31





Fig.32



11/15




Fig. 33




Fig.34

SECRET

12/15





Fig.36



WO 00/31758

13/15




Fig. 40




Fig. 41





Fig. 42



09831364-0022001

WO 00/31758

14/15

Fig.37





Fig.38



09831364-022901

15/15

Fig.44




Fig.43

